



Inspection Report

Envigo Global Services Inc.
925 County Road 381
Alice, TX 78332

Customer ID: **6906**
Certificate: **74-B-0332**
Site: 001
ENVIGO GLOBAL SERVICES INC

Type: ROUTINE INSPECTION
Date: 22-MAR-2023

3.75(a)

Housing facilities, general.

The covering for the roof insulation over enclosures 13/14 in KA 5 building is torn. Loose insulation is hanging over an enclosure housing non human primates . The insulation could easily fall into the animal enclosure and poses a risk of injury if ingested or contacted by the animals.

Housing facilities for nonhuman primates must be designed and constructed so that they are structurally sound for the species of nonhuman primates housed in them. They must be kept in good repair, and they must protect the animals from injury, contain the animals securely, and restrict other animals from entering. This area must be repaired or replaced an insulation over all enclosures properly maintained.

A maintenance crew was arriving at the building to repair the insulation covering as the inspector was leaving the area.

Corrected On : 3/22/2023

This inspection and exit briefing were conducted with facility employees.

Prepared By: ELIZABETH PANNILL
USDA, APHIS, Animal Care
Title: VETERINARY MEDICAL OFFICER

Date:
23-MAR-2023

Received by Title: Facility Representative

Date:
23-MAR-2023



Species Inspected

Cust No	Cert No	Site	Site Name	Inspection
6906	74-B-0332	001	ENVIGO GLOBAL SERVICES INC	22-MAR-2023

Count	Scientific Name	Common Name
003797	<i>Macaca fascicularis</i>	CRAB-EATING MACAQUE / CYNOMOLGUS MONKEY
003112	<i>Macaca mulatta</i>	RHESUS MACAQUE
006909	Total	