



Inspection Report

Circle B Farms L L C
1350 County Road 2445
Huntsville, MO 65259

Customer ID: **324104**
Certificate: **43-B-3698**
Site: 001
CIRCLE "B" FARMS L L C

Type: ROUTINE INSPECTION
Date: 18-FEB-2015

3.1(a)

HOUSING FACILITIES, GENERAL.

-Structure and protect the dogs from injury.

Inside the sheltered "Shih Tzu building", affecting 6 dogs, there is a 1 - 2 inch gap along the bottom of the wire divider panel. The inspectors observed a dog from one enclosure extending both front legs into another enclosure. This gap is large enough that the dogs could become injured or stuck. The licensee must repair this section of the wire divider and ensure that all enclosures protect the dogs from injury.

The ceiling above two enclosures, affecting 4 dogs, on the west side of the sheltered building "A building" is partially collapsed and is no longer structurally sound. A collapsed ceiling could injure the dogs. The licensee must repair this section of the ceiling. The licensee must ensure that housing facilities for dogs must be designed and constructed so that they are structurally sound and kept in good repair.

To be corrected by: February 24, 2015.

The inspection and exit interview were conducted with the licensee.

Additional Inspectors

Osborne Stephanie, Animal Care Inspector

Prepared By: CHAD PROCTOR, A C I USDA, APHIS, Animal Care

Date:
18-FEB-2015

Title: ANIMAL CARE INSPECTOR 6044

Received by Title: LICENSEE

Date:
18-FEB-2015



Species Inspected

Cust No	Cert No	Site	Site Name	Inspection
324104	43-B-3698	001	CIRCLE "B" FARMS L L C	18-FEB-15

Count	Scientific Name	Common Name
000089	<i>Canis lupus familiaris</i>	DOG ADULT
000018	<i>Canis lupus familiaris</i>	DOG PUPPY
000107	Total	