



Inspection Report

Christ S Beiler
124 Groffdale Rd
New Holland, PA 17557

Customer ID: **503628**
Certificate: **23-A-0669**
Site: 001
CHRIST S BEILER

Type: ROUTINE INSPECTION
Date: 17-OCT-2018

3.26(d)

FACILITIES, INDOOR.

Interior Surface. There is an open pit with slats in the new section of the building. The cement back wall has not be sealed in the new section. Interior building surfaces including walls and floor shall be constructed and maintained so that the surfaces are impervious to moisture so that they can be readily sanitized. The open pit needs be covered and the concrete back wall needs to be sealed or covered with an impervious surface so that these areas can be readily cleaned and sanitized when dirty. Correct by December 1, 2018.

This inspection and exit interview were conducted with the owner.

Prepared By: MARKMANN ROBERT, A C I USDA, APHIS, Animal Care

Date:
17-OCT-2018

Title: ANIMAL CARE INSPECTOR 1009

Received by Title: OWNER

Date:
17-OCT-2018



Species Inspected

Cust No	Cert No	Site	Site Name	Inspection
503628	23-A-0669	001	CHRIST S BEILER	17-OCT-18

Count	Scientific Name	Common Name
000198	<i>Cavia porcellus</i>	DOMESTIC GUINEA PIG
000198	Total	